

Exhibit – A

Pictures of Emergency Repairs at Fire Station 1



Cabinets and Sinks Removed:



Black Mold Found in the Wall:



Remove and Replace Corroded Cast Iron Plumbing:



After Black Mold Abatement and Improvements



