

Exhibit – A

Pictures of Fire Station #1 emergency repair work

Fire Station 1 Restroom Sharing Wall with Laundry Room:



Cabinets and Sinks Removed:



Black Mold Found in the Wall:



Remove and Replace Corroded Cast Iron Plumbing:





New ABS Plumbing Installed:



Wall Studs Mold Abatement and Coated Prior to Air Testing for Mold:

